MILL-MAX MFG.CORP.
190 Pine Hollow Road
Oyster Bay, NY 11771 U.S.A

PRODUCT CHANGE NOTICE

PCN Number: 26-1103B **Date Issued:** November 3, 2026

Series: Double tail header pins and 399-XX-0XX-21-300000 series socket.

Part Numbers Affected: 0290, 0315, 0504, 0505, 1083, 1090, 1221, 1752, 3006, 3039, 3077, 3169, 3400, 3401, 3402, 3404, 3405, 3406, 3409, 3410, 3411, 3413, 3516, 3790, 3796, 4242, 4259, 4516, 5005, 5012, 5016, 5107, 5113, 5301, 5503, 5504, 5505, 5509, 5510, 5511, 5752, 6218, 6289, 6458, 6585, 7007, 8006, 8404, 8608, 8685, 8859, 8885, 8919, 9036, 9051, 9075, 9218, 9260, & 399-XX-0XX-21-300000.

Type of Change: Web images being updated for advertising purposes.

Change will impact: **Form:** No **Fit:** No **Function:** No

Description of Change: The webpage and thumbnail images for the product series are being updated to better match latest layouts. No physical changes are being made to the parts. Minor dimensional corrections may be made to more accurately describe how the parts are being controlled.

Reason for the Change: Periodic updating of website images.

Effective Date: 11/3/26

Last Time Buy Date: Not applicable **Last Time Ship Date:** Not applicable

Replacement part number: Not applicable **Date available:** Not applicable

Contact Information: Contact Mill-Max sales at sales@mill-max.com for any questions about this notice.

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.