MILL-MAX MFG.CORP.
190 Pine Hollow Road
Oyster Bay, NY 11771 U.S.A

PRODUCT CHANGE NOTICE

PCN Number: 26-1120A **Date Issued:** November 20, 2026

Series: 801 & 803 Soldercup Termination SIP Sockets

Part Numbers Affected: 801-XX-0XX-10-007000 & 803-XX-0XX-10-007000

Type of Change: Dimensional change not critical to function.

Change will impact: **Form: Yes** **Fit: No** **Function: No**

Description of Change: Change the receptacle populating the assembly from the 1134-0 to the 1144-0. This results in the soldercup cut-out length increasing from .110” to .130”.

Reason for the Change: Product enhancement to improve manufacturability and stability of the receptacles in the insulator.

Effective Date: Previous design available at select distributors and factory until stock is depleted.

Last Time Buy Date: Not applicable **Last Time Ship Date:** Not applicable

Replacement part number: Not applicable **Date available:** Not applicable

Contact Information: Contact Mill-Max sales at sales@mill-max.com for any questions about this notice.

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.