



PRODUCT CHANGE NOTICE

PCN Number: 20-0218A

Date Issued: 2/18/2020

Series: Connector part numbers with 100 suffix (see list below)

Part Numbers Affected: See list below

Type of Change: Part number change only, there are no physical changes to the parts

Change will impact: **Form:** No **Fit:** No **Function:** No

Description of Change: Connector part numbers listed below, having a suffix of 100 will be invalid and replaced with part numbers ending in 000. These parts must now be ordered with the correct suffix of 000.

Reason for the Change: The 100-part number suffix was used to identify connectors with high temperature insulators, typically PCT, instead of standard temperature material, typically PBT. All insulator materials used for connectors has been high temperature since 2010, eliminating the need for the 100-part number suffix.

Effective Date: 3/15/2020

Last Time Buy Date: 3/1/2020

Last Time Ship Date: 3/15/2020

Replacement part number: See list below

Date available: Immediately

Contact Information: Contact Mill-Max Sales at sales@mill-max.com for any questions about this notice.

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



PRODUCT CHANGE NOTICE

| Discontinued Part Number | Replacement Part Number |
|--------------------------|-------------------------|
| 104-XX-3XX-41-780100 | 104-XX-3XX-41-780000 |
| 110-XX-XXX-10-003100 | 110-XX-XXX-10-003000 |
| 110-XX-XXX-41-001100 | 110-XX-XXX-41-001000 |
| 110-XX-XXX-41-801100 | 110-XX-XXX-41-801000 |
| 111-XX-XXX-41-001100 | 111-XX-XXX-41-001000 |
| 115-XX-XXX-41-001100 | 115-XX-XXX-41-001000 |
| 115-XX-XXX-41-003100 | 115-XX-XXX-41-003000 |
| 116-XX-XXX-41-006100 | 116-XX-XXX-41-006000 |
| 122-XX-XXX-41-001100 | 122-XX-XXX-41-001000 |
| 134-XX-XXX-00-020100 | 134-XX-XXX-00-020000 |
| 142-XX-XXX-00-591100 | 142-XX-XXX-00-591000 |
| 142-XX-XXX-00-592100 | 142-XX-XXX-00-592000 |
| 150-XX-XXX-00-001100 | 150-XX-XXX-00-001000 |
| 160-XX-XXX-00-001100 | 160-XX-XXX-00-001000 |
| 170-XX-XXX-00-001100 | 170-XX-XXX-00-001000 |
| 210-XX-XXX-41-001100 | 210-XX-XXX-41-001000 |
| 211-XX-XXX-41-001100 | 211-XX-XXX-41-001000 |
| 304-XX-XXX-41-770100 | 304-XX-XXX-41-770000 |
| 310-XX-XXX-41-001100 | 310-XX-XXX-41-001000 |
| 311-XX-XXX-41-001100 | 311-XX-XXX-41-001000 |
| 315-99-103-41-003100 | 315-99-103-41-003000 |
| 315-XX-XXX-41-001100 | 315-XX-XXX-41-001000 |
| 316-XX-XXX-41-003100 | 316-XX-XXX-41-003000 |
| 316-XX-XXX-41-006100 | 316-XX-XXX-41-006000 |

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



MILL-MAX MFG. CORP.
190 Pine Hollow Road
Oyster Bay, NY 11771 U.S.A

PRODUCT CHANGE NOTICE

| Discontinued Part Number | Replacement Part Number |
|---------------------------------|--------------------------------|
| 322-XX-XXX-41-001100 | 322-XX-XXX-41-001000 |
| 324-XX-XXX-41-002100 | 324-XX-XXX-41-002000 |
| 334-XX-XXX-00-010100 | 334-XX-XXX-00-010000 |
| 334-XX-XXX-00-020100 | 334-XX-XXX-00-020000 |
| 342-XX-XXX-00-592100 | 342-XX-XXX-00-592000 |
| 342-XX-XXX-00-593100 | 342-XX-XXX-00-593000 |
| 342-XX-XXX-00-594100 | 342-XX-XXX-00-594000 |
| 350-XX-XXX-00-000100 | 350-XX-XXX-00-000000 |
| 350-XX-XXX-00-006100 | 350-XX-XXX-00-006000 |
| 350-XX-XXX-00-107100 | 350-XX-XXX-00-107000 |
| 370-XX-XXX-00-001100 | 370-XX-XXX-00-001000 |
| 399-XX-XXX-00-009100 | 399-XX-XXX-00-009000 |
| 399-XX-XXX-10-003100 | 399-XX-XXX-10-003000 |
| 399-XX-XXX-10-009100 | 399-XX-XXX-10-009000 |
| 410-XX-XXX-41-001100 | 410-XX-XXX-41-001000 |
| 411-XX-XXX-41-001100 | 411-XX-XXX-41-001000 |
| 416-XX-XXX-41-001100 | 416-XX-XXX-41-001000 |
| 416-XX-XXX-41-006100 | 416-XX-XXX-41-006000 |
| 442-XX-XXX-00-591100 | 442-XX-XXX-00-591000 |
| 442-XX-XXX-00-592100 | 442-XX-XXX-00-592000 |
| 450-XX-XXX-00-001100 | 450-XX-XXX-00-001000 |
| 450-XX-XXX-00-006100 | 450-XX-XXX-00-006000 |
| 480-XX-XXX-00-001100 | 480-XX-XXX-00-001000 |

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



MILL-MAX MFG. CORP.
 190 Pine Hollow Road
 Oyster Bay, NY 11771 U.S.A

PRODUCT CHANGE NOTICE

| Discontinued Part Number | Replacement Part Number |
|---------------------------------------|---------------------------------------|
| 499-XX-XXX-10-003100 | 499-XX-XXX-10-003000 |
| 499-XX-XXX-10-009100 | 499-XX-XXX-10-009000 |
| 605-XX-XXX-11-480100 | 605-XX-XXX-11-480000 |
| 714-XX-XXX-31-018100 | 714-XX-XXX-31-018000 |
| 800-XX-XXX-10-001100 | 800-XX-XXX-10-001000 |
| 800-XX-XXX-10-002100 | 800-XX-XXX-10-002000 |
| 800-XX-XXX-20-000100 | 800-XX-XXX-20-000000 |
| 800-XX-XXX-62-001100 | 800-XX-XXX-62-001000 |
| 801-XX-XXX-10-001100 | 801-XX-XXX-10-001000 |
| 801-XX-XXX-10-012100 | 801-XX-XXX-10-012000 |
| 802-XX-XXX-10-001100 | 802-XX-XXX-10-001000 |
| 802-XX-XXX-10-002100 | 802-XX-XXX-10-002000 |
| 802-XX-XXX-20-001100 | 802-XX-XXX-20-001000 |
| 802-XX-XXX-61-001100 | 802-XX-XXX-61-001000 |
| 917-XX-XXX-41-005100 | 917-XX-XXX-41-005000 |
| SEE NEXT PAGE FOR CUSTOM PARTS | SEE NEXT PAGE FOR CUSTOM PARTS |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



MILL-MAX MFG. CORP.
190 Pine Hollow Road
Oyster Bay, NY 11771 U.S.A

PRODUCT CHANGE NOTICE

| Discontinued Part Number | Replacement Part Number |
|---------------------------------|--------------------------------|
| S106-XX-XXX-30-680100 | S106-XX-XXX-30-680000 |
| S295-93-328-30-571100 | S295-93-328-30-571000 |
| S340-XX-XXX-30-780100 | S340-XX-XXX-30-780000 |
| S388-13-106-12-250100 | S388-13-106-12-250000 |
| S394-90-114-00-040100 | S394-90-114-00-040000 |
| S396-XX-00X-00-930100 | S396-XX-00X-00-930000 |
| S397-00-006-00-720100 | S397-00-006-00-720000 |
| S450-XX-XXX-32-440100 | S450-XX-XXX-32-440000 |
| S497-00-016-00-610100 | S497-00-016-00-610000 |
| S498-93-208-30-971100 | S498-93-208-30-971000 |
| S605-93-628-12-710100 | S605-93-628-12-710000 |
| S702-13-216-16-850100 | S702-13-216-16-850000 |
| S703-XX-XXX-47-052100 | S703-XX-XXX-47-052000 |
| S794-93-120-21-620100 | S794-93-120-21-620000 |
| S795-43-000-00-510100 | S795-43-000-00-510000 |
| S795-XX-006-00-510100 | S795-XX-006-00-510000 |
| S797-30-005-00-520100 | S797-30-005-00-520000 |
| S816-13-004-16-821100 | S816-13-004-16-821000 |
| S898-00-024-00-440100 | S898-00-024-00-440000 |
| S898-00-024-00-450100 | S898-00-024-00-450000 |
| | |
| | |

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.