

## PRODUCT CHANGE NOTICE

**PCN Number:** 22-0901A

Date Issued: September 1, 2022

Series: Pins in the following series: 3975, 5979, 6932, & 7979.

Part Numbers Affected: See table below

Type of Change: Part numbering change only, no physical changes to the parts

Change will impact: Form: No Fit: No Function: No

**Description of Change:** Changed the part number for 3975, 5979, 6932, & 7979 series press-fit pins.

**Reason for the Change:** To consolidate comparable product series and make like parts easier to find.

Effective Date: Immediately

Last Time Buy Date: Not applicable

Replacement part number: Not applicable

Last Time Ship Date: Not applicable

Date available: Not applicable

**Contact Information:** Contact Mill-Max sales at <u>sales@mill-max.com</u> for any questions about this notice.

Discontinued Part Number	Replacement Part Number
3975-0-00-15-00-03-0	3977-1-00-15-00-00-03-0
3975-0-00-80-00-03-0	3977-1-00-80-00-03-0
5979-0-00-15-00-03-0	8979-1-00-15-00-00-03-0
5979-0-00-80-00-03-0	8979-1-00-80-00-03-0
6932-0-00-15-00-03-0	8932-1-00-15-00-00-03-0
6932-0-00-80-00-03-0	8932-1-00-80-00-03-0
7979-0-00-15-00-03-0	8979-2-00-15-00-00-03-0

## MILL-MAX ELECTRONIC INTERCONNECT COMPONENTS

<u>www.mill-max.com</u>

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.