

## PRODUCT CHANGE NOTICE

**PCN Number:** 25-0421A

Date Issued: April 21, 2025

Series: 0439 receptacle with a standard tail

Part Numbers Affected: 0439-0-15-15-04-27-04-4

Type of Change: Part Number, change the last digit of the part number from 4 to 0.

Change will impact: Form: No Fit: No Function: No

**Description of Change:** The part number of the 0439-0-15-15-04-27-04-**4** will change to 0439-0-15-15-04-27-04-**0**.

Reason for the Change: The part number is being corrected to fix an error.

Effective Date: 4/1/25

Last Time Buy Date: Not applicable Last Time Ship Date: Not applicable

Replacement part number: Not applicable

Date available: Not applicable

**Contact Information:** Contact Mill-Max sales at <u>sales@mill-max.com</u> for any questions about this notice.

MILL-MAX ELECTRONIC INTERCONNECT COMPONENTS

<u>www.mill-max.com</u>

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.