



PRODUCT DISCONTINUATION NOTICE

PDN Number: 20-0601A

Date Issued: June 01, 2020

Series: Standard SMT and through hole Tin/lead plated PLCC sockets (various positions, tube and tape and reel packaged, lubricated and non-lubricated).

Discontinued Part Numbers: 940-99-XXX-XX-X0X00X (See table below)

Reason for discontinuation: No longer available from supplier

Effective Date: Immediate

Last Time Buy Date: N/A (No Stock)

Affected Part Numbers		
Discontinued Part Numbers (Tin/lead Plating)	Alternative Part Numbers (Pure Tin Plating)	Packaging Type
940-99-020-17-400000	940-44-020-17-400000	Tube
940-99-020-17-400004	940-44-020-17-400004	Tape & Reel
940-99-020-17-401000	Not Available	-
940-99-020-17-401004	Not Available	-
940-99-028-17-400000	940-44-028-17-400000	Tube
940-99-028-17-400004	940-44-028-17-400004	Tape & Reel
940-99-028-17-401000	Not Available	-
940-99-028-17-401004	Not Available	-
940-99-032-17-400000	940-44-032-17-400000	Tube
940-99-032-17-400004	940-44-032-17-400004	Tape & Reel
940-99-032-17-401000	Not Available	-
940-99-032-17-401004	Not Available	-
940-99-044-17-400000	940-44-044-17-400000	Tube
940-99-044-17-400004	940-44-044-17-400004	Tape & Reel
940-99-044-17-401000	Not Available	-
940-99-044-17-401004	Not Available	-
940-99-052-17-400000	940-44-052-17-400000	Tube
940-99-052-17-400004	940-44-052-17-400004	Tape & Reel

MILL-MAX ELECTRONIC INTERCONNECT COMPONENTS www.mill-max.com

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.



PRODUCT DISCONTINUATION NOTICE

940-99-052-17-401000	Not Available	-
940-99-052-17-401004	Not Available	-
940-99-068-17-400000	940-44-068-17-400000	Tube
940-99-068-17-400004	940-44-068-17-400004	Tape & Reel
940-99-068-17-401000	Not Available	-
940-99-068-17-401004	Not Available	-
940-99-084-17-400000	940-44-084-17-400000	Tube
940-99-084-17-400004	940-44-084-17-400004	Tape & Reel
940-99-084-17-401000	Not Available	-
940-99-084-17-401004	Not Available	-
940-99-020-24-000000	940-44-020-24-000000	Tube
940-99-020-24-001000	Not Available	-
940-99-028-24-000000	940-44-028-24-000000	Tube
940-99-028-24-001000	Not Available	-
940-99-032-24-000000	940-44-032-24-000000	Tube
940-99-032-24-001000	Not Available	-
940-99-044-24-000000	940-44-044-24-000000	Tube
940-99-044-24-001000	Not Available	-
940-99-052-24-000000	940-44-052-24-000000	Tube
940-99-052-24-001000	Not Available	-
940-99-068-24-000000	940-44-068-24-000000	Tube
940-99-068-24-001000	Not Available	-
940-99-084-24-000000	940-44-084-24-000000	Tube
940-99-084-24-001000	Not Available	-
940-99-100-24-000000	940-44-100-24-000000	Tube
940-99-100-24-001000	Not Available	-

Contact Information: Contact Mill-Max sales at sales@mill-max.com for any questions about this notice.

MILL-MAX ELECTRONIC INTERCONNECT COMPONENTS www.mill-max.com

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.